

“SOLAR 1” OIL RECOVERY – DAILY PROGRESS REPORT

DPR No.:	011	Date:	20 th March 2007
-----------------	-----	--------------	-----------------------------

ASSETS

Name	Location
“ALLIED SHIELD” – DP Vessel	Wreck site, 10° 15.5’N, 122° 29.15’E.
Sonsub Discovery 5 & Triton 4 -ROV	On board “ALLIED SHIELD”
Sonsub Oil Recovery Equipment	On board “ALLIED SHIELD”
“ATLAS” – OSR Barge	Bacolod anchorage
“MARANAW” – OSR Tug	On site
“BALINTAWAK” – OSR Tug	On site
Designated OSR Aircraft	Stand by

PERSONNEL ON BOARD

Personnel	Total On Board
Marine Crew	22
Sonsub	27
Others	1
Total	50

WEATHER CONDITIONS

Time	Wind Speed (Kts)	Wind Direction	Wave Height (m)	Remarks
0600	13	NNE	1	
1200	8	NE	0.5	
1800	15	NNE	1	
2400	16	NE	1.5	

SUMMARY OF ACTIVITIES

Time	Description
0000	“ALLIED SHIELD” located over wreck location
0800	OSR exercise conducted with vessels “MARANAW” and “BALINTAWAK”
1200	Completed penetration of tank No.4 starboard. No oil found.
1330	Complete installation of tank No.4 starboard hull plug
1700-1745	Two PCG officers board for operational briefing
1830	Commence installation of hull valve at No.3 port
	Continuous preparation of main deck for hull valve installations
2359	End of day

PLANNED ACTIVITIES FOR NEXT 24 HOURS

Continue penetration of tanks through installed hull safety valves
Commence shuttle operations as required as tanks are penetrated
“MARANAW” leave location to re-fuel

Jon Walker
London Offshore Consultants
Client Representative