

## “SOLAR 1” OIL RECOVERY – DAILY PROGRESS REPORT

<b>DPR No.:</b>	013	<b>Date:</b>	22 <sup>nd</sup> March 2007
-----------------	-----	--------------	-----------------------------

ASSETS	
Name	Location
“ALLIED SHIELD” – DP Vessel	Wreck site, 10° 15.5’N, 122° 29.15’E.
Sonsub Discovery 5 & Triton 4 -ROV	On board “ALLIED SHIELD”
Sonsub Oil Recovery Equipment	On board “ALLIED SHIELD”
“ATLAS” – OSR Barge	Bacolod anchorage
“MARANAW” – OSR Tug	On site
“BALINTAWAK” – OSR Tug	Bacolod for replenishment
Designated OSR Aircraft	Stand by

PERSONNEL ON BOARD	
Personnel	Total On Board
Marine Crew	22
Sonsub	28
Others	1
<b>Total</b>	<b>51</b>

WEATHER CONDITIONS				
Time	Wind Speed (Kts)	Wind Direction	Wave Height (m)	Remarks
0600	17	NNE	1.5	
1200	14	NE	1.5	
1800	17	NE	1	
2400	18	NE	1.5	

SUMMARY OF ACTIVITIES	
Time	Description
0000	“ALLIED SHIELD” located over wreck location
	Continuous ROV preparation of main for installation of hull safety valves
0735	“BALINTAWAK” departs to Bacolod for replenishment
1000	Commence installation of water injection safety valve at tank 3P
1715-1740	PCG officer on board for operational briefing
1740	Complete installation of water injection safety valve at tank 3P
1850	Positioning of shuttle over 3P hull safety valve
2120	Commence recovering oil from tank 3P
2210	Suspend oil recovery from tank 3P. Hull safety valve closed.
	Continuous operations to install hull safety valve at 5P
2359	End of day

<b>PLANNED ACTIVITIES FOR NEXT 24 HOURS</b>
Continue oil recovery from 3P
Install hull safety valve at 5P
Commence recovery of oil from tank 5P
Continuous operations to prepare for installation of hull safety valves

Jon Walker

London Offshore Consultants

Client Representative