

“SOLAR 1” OIL RECOVERY – DAILY PROGRESS REPORT

DPR No.:	019	Date:	28th March 2007
-----------------	-----	--------------	-----------------

ASSETS	
Name	Location
“ALLIED SHIELD” – DP Vessel	Wreck site, 10° 15.5’N, 122° 29.15’E.
Sonsub Discovery 5 & Triton 4 -ROV	On board “ALLIED SHIELD”
Sonsub Oil Recovery Equipment	On board “ALLIED SHIELD”
“ATLAS” – OSR Barge	Bacolod anchorage
“MARANAW” – OSR Tug	On site
“BALINTAWAK” – OSR Tug	On site
Designated OSR Aircraft	Stand by

PERSONNEL ON BOARD	
Personnel	Total On Board
Marine Crew	22
Sonsub	26
Others	1
Total	49

WEATHER CONDITIONS				
Time	Wind Speed (Kts)	Wind Direction	Wave Height (m)	Remarks
0600	13	NE	1	
1200	16	N	1	
1800	16	NE	1	
2400	18	NNE	1	

SUMMARY OF ACTIVITIES	
Time	Description
0000	“ALLIED SHIELD” located over wreck location
	Continuous preparation of main deck in way of 1P, 2S and 1S
0740	PCG officer on board for operational briefing
1153	Penetrate deck at 2P through oil extraction hull safety valve.
1438	Penetrate deck at 2S through oil extraction hull safety valve. No oil found
2100-2120	Complete oil recovery at 5P oil extraction hull safety valve to shuttle
2200	Commence oil recovery at 2P oil extraction hull safety valve to shuttle
2359	End of day

PLANNED ACTIVITIES FOR NEXT 24 HOURS
Prepare main deck for installation of oil extraction hull safety valve at 1S.

Penetrate deck at oil extraction hull safety valves at 1P, 1S

Recover oil to shuttle, if found, from oil extraction hull safety valves at 2P, 1S, 1P
--

Jon Walker, London Offshore Consultants, Client Representative