

“SOLAR 1” OIL RECOVERY – DAILY PROGRESS REPORT

DPR No.:	020	Date:	29th March 2007
-----------------	-----	--------------	-----------------

ASSETS	
Name	Location
“ALLIED SHIELD” – DP Vessel	Wreck site, 10° 15.5’N, 122° 29.15’E.
Sonsub Discovery 5 & Triton 4 -ROV	On board “ALLIED SHIELD”
Sonsub Oil Recovery Equipment	On board “ALLIED SHIELD”
“ATLAS” – OSR Barge	Bacolod anchorage
“MARANAW” – OSR Tug	On site
“BALINTAWAK” – OSR Tug	On site
Designated OSR Aircraft	Stand by

PERSONNEL ON BOARD	
Personnel	Total On Board
Marine Crew	22
Sonsub	26
Others	1
Total	49

WEATHER CONDITIONS				
Time	Wind Speed (Kts)	Wind Direction	Wave Height (m)	Remarks
0600	17	NE	1.5	
1200	12	NE	1.5	
1800	15	NE	1.5	
2400	17	NNE	1.5	

SUMMARY OF ACTIVITIES	
Time	Description
0000	“ALLIED SHIELD” located over wreck location
0100	Complete oil recovery at 2P oil extraction safety valve to shuttle
	Continuous deck preparation and installation of hull safety valves at 1P and 1S
1535	Penetrate deck at 1P through oil extraction safety valve. No oil found.
2052	Penetrate deck at 1S through oil extraction safety valve. No oil found.
2359	End of day

PLANNED ACTIVITIES FOR NEXT 24 HOURS
Post survey of all cargo tanks

Jon Walker, London Offshore Consultants, Client Representative