

“SOLAR 1” OIL RECOVERY – DAILY PROGRESS REPORT

DPR No.:	021	Date:	30th March 2007
-----------------	-----	--------------	-----------------

ASSETS	
Name	Location
“ALLIED SHIELD” – DP Vessel	Wreck site, 10° 15.5’N, 122° 29.15’E.
Sonsub Discovery 5 & Triton 4 -ROV	On board “ALLIED SHIELD”
Sonsub Oil Recovery Equipment	On board “ALLIED SHIELD”
“ATLAS” – OSR Barge	Bacolod anchorage
“MARANAW” – OSR Tug	Bacolod for replenishment
“BALINTAWAK” – OSR Tug	On site
Designated OSR Aircraft	Stand by

PERSONNEL ON BOARD	
Personnel	Total On Board
Marine Crew	22
Sonsub	26
Others	1
Total	49

WEATHER CONDITIONS				
Time	Wind Speed (Kts)	Wind Direction	Wave Height (m)	Remarks
0600	16	NNE	1.5	
1200	6	NE	1	
1800	4	WNW	0.5	
2400	10	NNE	1	

SUMMARY OF ACTIVITIES	
Time	Description
0000	“ALLIED SHIELD” located over wreck location
	Commence post operational survey of all cargo tanks using shuttle to recover oil remnants.
0350	Open 5P tank hatch, tank empty
	Preparation of deck at 4P for installation of oil extraction safety valve.
0740	PCG officer on board for operational briefing
1147	Install oil extraction safety valve at 4P
1600	Open 1P tank hatch, tank empty
1705	PCG officer on board for operational briefing
1740	Open 2S tank hatch, tank empty
1830	Open 3S tank hatch, tank empty
1930	Open 4S tank hatch, tank empty
2140	Open oil extraction safety valve at 4P to recover oil remnants

2359	End of day
------	------------

PLANNED ACTIVITIES FOR NEXT 24 HOURS

Complete post operational survey

Recover shuttle and discharge oil to ISO tank

Jon Walker
London Offshore Consultants, Client Representative
